

NYSDEC SPILL REPORT FORM

DEC REGION# 3 (New Paltz) SPILL NUMBER 9708454 OCT 20 1997  
 SPILL NAME: WATCHTOWER DEC LEAD: \_\_\_\_\_  
 CALLER'S NAME: \_\_\_\_\_ NOTIFIER'S NAME: \_\_\_\_\_  
 CALLER'S AGENCY: WATCHTOWER NOTIFIER'S AGENCY: WATCHTOWER *A. DUMAS*  
 CALLER'S PHONE: \_\_\_\_\_ EXT. \_\_\_\_\_ NOTIFIER'S PHONE: \_\_\_\_\_ EXT. \_\_\_\_\_

SPILL DATE: 10/10/97 *10/10/97* TIME: 14:00  
 CALL RECEIVED DATE: 10/20/97 TIME: 10:59 RECEIVED BY CID #: 286

Material Spilled	Mat. Class	Am't Spilled	Units	Am't Recovered
1) <u>WASTE OIL</u>	<u>(Pet)</u> Haz-Other-Unk.	<u>100</u>	<u>(Gal)</u> Lbs	<u>100</u>
2) _____	Pet-Haz-Other-Unk.	_____	Gal - Lbs	_____
3) _____	Pet-Haz-Other-Unk.	_____	Gal - Lbs	_____
4) _____	Pet-Haz-Other-Unk.	_____	Gal - Lbs	_____

FILE COPY

<b>SPILL LOCATION</b>	<b>POTENTIAL SPILLER</b>
PLACE: <u>WATCHTOWER</u>	NAME: <u>WATCHTOWER</u>
STREET: <u>900 RED MILL ROAD</u>	STREET: <u>25 COLUMBIA HEIGHTS</u>
T/CIV: <u>WALKILL</u> CO: <u>ULSTER</u>	CITY: <u>BROOKLYN</u>
CONTACT: _____	STATE: <u>NY</u> ZIP: <u>11201-</u>
PHONE: _____ EXT. _____	CONTACT: <u>DEAN IALEGHANY</u>
	PHONE: _____ EXT. _____

<b>SPILL CAUSE</b>	<b>SPILL SOURCE</b>
<u>(Human Error)</u> Tank Test Failure	Gas Station
Human Error	Private Dwelling
Equipment Failure	Non-Maj Facility
Vandalism	<u>(Comm/Indust)</u>
Tank Test Failure	Comm. Vehicle
Housekeeping	Tank Truck
Deliberate	Major Facility
Abandoned Drums	Unknown
Tank Failure	
Tank Overfill	
Other	
Unknown	

<b>RESOURCE AFFECTED</b>	<b>SPILL REPORTED BY</b>
<u>(On Land)</u> Groundwater	<u>(Responsible Party)</u> Tank Tester
In Sewer Surface Water	Affected Persons DEC
Air	Police Department Citizen
	Fire Department Health Dept.
	Local Agency
	Federal Gov't
	Other

CALLER REMARKS: BACK HOE ACCIDENTAL HIT TO DRUMS OF WASTE OIL, ONTO CLAY. CLEANED UP.  
10/20 - I called (11:20 am) spill occurred on 10/10; it affected a 10 sq foot section of drums. They dug up the affected soil, put it in drums, and it will be disposed of w/ these regular waste hauler.

<b>PBS Number</b>	<b>Tank Number</b>	<b>Tank Size</b>	<b>Test Method</b>	<b>Leak Rate</b>
<u>Ashland Chemical</u>	<u>0</u>	<u>0</u>	<u>None</u>	<u>None</u>

PAGED ON 1 1 0 hrs

PRIMARY CONTACT CALLED DATE: \_\_\_\_\_ TIME: \_\_\_\_\_ hrs. REACHED DATE: \_\_\_\_\_ TIME: \_\_\_\_\_ hrs.  
 SECONDARY CONT. CALLED DATE: \_\_\_\_\_ TIME: \_\_\_\_\_ hrs. FAXED BY CID#: 286

PIN #	I & A	LOG#	ISR to Original Office
Cleanup Ceased	Meets St'ds	NO	Last Inspection
RP-CUI	ENF-INIT	INVS-COM	CAP
UST Trust Eligible	NO	Site: A B <u>(C)</u> D E	Resp. Party 1 2 <u>(3)</u> 4 5 6
Reg Class Date	<u>10/20/97</u>		

Names and Contact details removed from Original document by publisher

Page 1 of 1 Spill No.: 97-08454 Pin No.: \_\_\_\_\_

Name: Watchtower

Location: 900 Red Mills Rd. Wallkill

Date of Inspection: 10-20-97 County: Ulster

Inspection: 10-20-97 or Telephone Conversation \_\_\_\_\_

Contact Person: \_\_\_\_\_

**SITE ACTIVITY:** 10-20-97 Met on site with Watchtower Rep. \_\_\_\_\_ brought me to area where spill occurred. 55 gal drums (2) were punctured by backhoe and lost contents (waste oil) onto ground (construction area). Because ground was clay & oil did not soak in easily, they applied sand to spill. Then they filled up 10 or 11 55 gallon drums with the contaminated sand & clay underneath. These were placed in a secure area on site and samples were obtained for disposal purposes. Ashland Chemical is their waste hauler for other hazardous materials produced on site & will also be used for this disposal. I asked Scott to submit waste manifest (copy) when available and informed him that this spill should have been reported w/I 2 hrs. of discovery, next time they will be ticketed.

**FURTHER ACTION NEEDED:** \_\_\_\_\_

PREPARED BY: J. McCarthy DATE: DATE \_\_\_\_\_